

# DP-301U Firmware Release Note

**Firmware: v2.10**

**Hardware: B1**

**Date: Jan 1st, 2006**

Enhancement:

1. Supports GDI printers (Windows Graphical Device Interface), also called as host-based printers.

**HP** LaserJet 1010, 1022 , 1160

**EPSON** Color LaserJet 2600N , 3500 , 3550

**Firmware: v2.00**

**Hardware: B1**

**Date: June 21, 2005**

Problems Resolved:

1. Fixed using UPnP IP Add Printer Problem.
2. Server Name characters allowed :

'0' - '9'

'A' - 'Z'

'a' - 'z'

'.'

other special characters are not allowed.

3. Change message as "Print Server is re-starting, click here to return to web configuration, and it may take a few seconds"
4. Display error message "Invalid Default Gateway setting" on Test e-mail notification if IP address is Fixed IP mode and Default Gateway is 0.0.0.0
5. Fixed test e-mail notification checking --
  - \* Check "Print Server E-mail Address", if blank, then display "Invalid e-mail setting".
  - \* Check "DNS Address", if it is 0.0.0.0 under Fixed IP mode, then display "Invalid DNS setting".
  - \* Change "E-mail is sent" as "E-mail is being sent".
6. Fixed SNMP 32 Bytes Community Name Problem
7. Fixed DHCP get IP problem from Sercomm's Router

Enhancements:

1. Add Internal Version HTML file -- [http://ip\\_address/version.htm](http://ip_address/version.htm) --> Version  
Display : v2.00 Build 1 - 2005-05-26
2. Support MAC OS 10.3 IPP Printing